

20020721.ba v03\_n367.bam.20020721

>From ???@??? Sun Jul 21 15:07:53 2002 -0500  
Message-Id: <200207212007.g6LK7VEV025822@sco.theporch.com>  
Date: Sun, 21 Jul 2002 15:07:04 CDT  
From: Old Tube Radios <boatanchors@theporch.com>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: BOATANCHORS digest 3367

BOATANCHORS Digest 3367

Topics covered in this issue include:

- 1) Mackay Marine 3030A  
by Al Klase <skywaves@bw.webex.net>
- 2) 600 kHz carrier current(?) tx FS, \$35 shipped  
by Andy Wallace <wallace@world.std.com>
- 3) Collins 312B-3 Spkr Wanted  
by Robert Kemp <rkemp@mr.net>
- 4) Texas City, TX hamfest report  
by <plmills@attglobal.net>
- 5) RE: Texas City, TX hamfest report  
by "WF2U" <wf2u@starband.net>
- 6) Strange Signal Alert??!!  
by "Sandy, W5TVW" <ebjr@i-55.com>
- 7) Re: Strange Signal Alert??!!  
by Bob Roehrig <broehrig@aurora.edu>
- 8) Re: Strange Signal Alert??!!  
by W5USM@aol.com
- 9) Re: Strange Signal Alert??!!  
by Al Klase <skywaves@bw.webex.net>
- 10) Stuff for sale  
by "Richard Dillman" <ddillman@igc.org>
- 11) Sad TMC  
by "Richard Dillman" <ddillman@igc.org>
- 12) Re: Strange Signal Alert??!!  
by "Sandy, W5TVW" <ebjr@i-55.com>
- 13) Soldering and high impedance phones.  
by "Tom and Silvia Lewandowski" <lewandowski@usfamily.net>
- 14) Re: Soldering and high impedance phones.  
by "ed sharpe" <esharpe@uswest.net>
- 15) FW: [Heathkit] WTB: GD-18  
by "Gary Harmon" <gharmon@idworld.net>
- 16) spam block test  
by "Robert W. Downs" <RWDowns\_WA5CAB@compuserve.com>
- 17) TM 11-5820-520-35 (AN/GRC-106)  
by "Robert W. Downs" <RWDowns\_WA5CAB@compuserve.com>
- 18) ADMINISTRIVIA: Over Quoting

- by listown@nanniandjack.com (Mail List Owner)
- 19) Collins 51S-1 Owners?  
by "Richard Dillman" <ddillman@igc.org>
  - 20) RE: FWD:USS Requin Needs Tubes & WRT2 Info  
by "Robert W. Downs" <RWDowns\_WA5CAB@compuserve.com>
  - 21) Hammarlund Historian Website rebirth  
by "Al Parker" <anchor@ec.rr.com>
  - 22) Hammarlund Historian Website rebirth  
by "Al Parker" <anchor@ec.rr.com>

-----  
Message-ID: <3D396A07.1FE2AA92@bw.webex.net>  
Date: Sat, 20 Jul 2002 09:47:52 -0400  
From: Al Klase <skywaves@bw.webex.net>  
MIME-Version: 1.0  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: Mackay Marine 3030A  
Content-Type: text/plain; charset=us-ascii  
Content-Transfer-Encoding: 7bit

Gentlemen,

I'm working on an ITT Mackay Marine 3030A receiver. Do any of you have documentation on or experience with this LF/HF receiver?

It works, but is extremely noisy. Gain through the front end is approximately unity, which is what I'd expect. However, when I connect my shop receiver to the 5-Mhz IF port of the second mixer I have S-9 white noise.

Should I just write this off as yet another high-end radio with synthesizer problems that no one's going to fix?

73,  
Al

--  
Al Klase - N3FRQ  
skywaves@bw.webex.net  
Flemington, NJ 08822  
Web Page: <http://www.webex.net/~skywaves/home.htm>

-----  
From: Andy Wallace <wallace@world.std.com>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: 600 kHz carrier current(?) tx FS, \$35 shipped  
Date: Sat, 20 Jul 2002 12:48:16 -0400

Message-ID: <mk4jjugl89bporlob0akbk8sneb2vagiks@4ax.com>

MIME-Version: 1.0

Content-Type: text/plain; charset=us-ascii

Content-Transfer-Encoding: 7bit

Have something which I bought from the BA list a few years back and it has not moved from the spot since. You know the way it is!

MFR is  
LOW POWER BROADCAST EQUIPMENT  
248 SWEDES FORD ROAD  
MALVERN, Penna

Coupling box to interface to AC line (I assume) marked  
RC-T3A, s/n 118  
tested 10/65

Transmitter is labelled MARK III with the same date.

Base about 6x10", beefy and professional construction  
Large power xfmr and UTC varimatch CVM-0 12W mod xfmr  
With 600 kHz xtal, tubes 6CA4 and two 6AL11.  
600Z line input and gain pot, two terminal output and "tune for max" adjustment.  
Untested.

Will sell for \$35 shipped in the U.S. only.

--Andy  
wallace@theworld.com

-----  
Message-ID: <3D39AEA0.8090204@mr.net>

Date: Sat, 20 Jul 2002 13:40:32 -0500

From: Robert Kemp <rkemp@mr.net>

MIME-Version: 1.0

To: Old Tube Radios <boatanchors@theporch.com>

Subject: Collins 312B-3 Spkr Wanted

Content-Type: text/plain; charset=us-ascii; format=flowed

Content-Transfer-Encoding: 7bit

Anyone have a 312B-3 speaker f/s.  
Need a winged emblem one. Doesn't have to be perfect....just  
straight and functional.  
Tnx

-----

Message-ID: <001701c2302a\$57b059d0\$83e4400c@W5BVB>  
From: <plmills@attglobal.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: Texas City, TX hamfest report  
Date: Sat, 20 Jul 2002 15:16:32 -0500  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: 7bit

I showed up about 7 a.m. but the doors did not open for non-vendors until 8 so I just watched people move stuff inside. There was virtually no tailgate in the parking lot unlike past years.

My bargain for the day was about a dozen new Xcelite screwdrivers and nutdrivers for \$1 each. I arrived about 2 minutes too late at a table where a B&W 5100 transmitter had just been sold for \$80 along with a decent looking Hammarlund HQ-170 for \$60. The same seller had an R-174 receiver with attached mil power supply for \$60 but I passed since I was not familiar with it.

This one looks like it may be a dying hamfest as there were more empty tables than last year.

73, Phil  
W5BVB

-----  
From: "WF2U" <wf2u@starband.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: RE: Texas City, TX hamfest report  
Date: Sat, 20 Jul 2002 16:58:33 -0400  
Message-ID: <NABBLNEJDDKECLKHCAAPAEMCHOAA.wf2u@starband.net>  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: 7bit

The R-174/ARR-5 complete with the power supply for \$60? What a steal!! Would have been a bargain for double the price if it's in nice shape...

73, Meir WF2U

-----Original Message-----  
From: owner-boatanchors@theporch.com

[mailto:owner-boatanchors@theporch.com] On Behalf Of plmills@attglobal.net  
Sent: Saturday, July 20, 2002 4:17 PM  
To: Old Tube Radios  
Subject: Texas City, TX hamfest report

I showed up about 7 a.m. but the doors did not open for non-vendors until 8 so I just watched people move stuff inside. There was virtually no tailgate in the parking lot unlike past years.

My bargain for the day was about a dozen new Xcelite screwdrivers and nutdrivers for \$1 each. I arrived about 2 minutes too late at a table where a B&W 5100 transmitter had just been sold for \$80 along with a decent looking Hammarlund HQ-170 for \$60. The same seller had an R-174 receiver with attached mil power supply for \$60 but I passed since I was not familiar with it.

This one looks like it may be a dying hamfest as there were more empty tables than last year.

73, Phil  
W5BVB

-----  
Message-ID: <000901c2303a\$78b724a0\$d9a2cdd1@ebjr>  
From: "Sandy, W5TVW" <ebjr@i-55.com>  
To: Old Tube Radios <boatanchors@theporch.com>  
Cc: <K1DW@aol.com>, <KC1Z@aol.com>,  
"Plez Z Reid, W1CCX" <103677.3511@compuserve.com>,  
"Walt, KA1MM" <ka1mm@snet.net>, "Frank Thrash, W4DLZ" <w4dlz@arrl.net>,  
"Frank Thrash @ snakebite" <maryland@snakebite.com>  
Subject: Strange Signal Alert??!!  
Date: Sat, 20 Jul 2002 17:11:15 -0500  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: 7bit

Hello All,  
Please listen up on HF. I am getting a signal that sound like someone using AMTOR or PACTOR generating white noise spurious signals. They seem to peak out around 14 and 15 Mhz. but I can't find any signal that matches the timing of the noise. Is anyone else hearing this? Signals on the hambands seems weak to non existant. I

suspect a solar blackout or partial one at least.  
I have seen other funny and wierd signals during severe  
ionospheric blackout events in the past, this may be the same.  
Makes me always question my equipment!! I was hearing strange overloading  
phenomena on my Hallicrafters SR-400's receiver as well.

Anyone else having trouble today/last night?

73,  
Sandy W5TVW

-----  
Date: Sat, 20 Jul 2002 18:14:39 -0500 (CDT)  
From: Bob Roehrig <broehrig@aurora.edu>  
To: Old Tube Radios <boatanchors@theporch.com>  
cc: Boatanchors <boatanchors@sco.theporch.com>  
Subject: Re: Strange Signal Alert??!!  
Message-ID: <Pine.OSF.4.43.0207201813500.322128-100000@mail.aurora.edu>  
MIME-Version: 1.0  
Content-Type: TEXT/PLAIN; charset=US-ASCII

On Sat, 20 Jul 2002, Sandy, W5TVW wrote:

> Hello All,  
> Please listen up on HF. I am getting a signal that sound like someone  
> using AMTOR or PACTOR generating white noise spurious signals.  
> They seem to peak out around 14 and 15 Mhz. but I can't find any  
> signal that matches the timing of the noise.  
> Is anyone else hearing this?

Nothing out of the ordinary here at 2300Z Just heard a LOUD EA4 calling  
CQ on SSB.....

Bob Roehrig  
Aurora University Telecom/IS dept.  
broehrig@aurora.edu  
73 de K9EUI

-----  
From: W5USM@aol.com  
Message-ID: <120.137d8b19.2a6b4c50@aol.com>  
Date: Sat, 20 Jul 2002 19:29:20 EDT  
Subject: Re: Strange Signal Alert??!!  
To: Old Tube Radios <boatanchors@theporch.com>  
CC: K1DW@aol.com, KC1Z@aol.com, 103677.3511@compuserve.com, ka1mm@snet.net,  
w4dlz@arrl.net, maryland@snakebite.com  
MIME-Version: 1.0

Content-Type: multipart/alternative;  
boundary="part1\_120.137d8b19.2a6b4c50\_boundary"

--part1\_120.137d8b19.2a6b4c50\_boundary  
Content-Type: text/plain; charset="US-ASCII"  
Content-Transfer-Encoding: 7bit

There was a major SID at approximately 2115Z that wiped out the bands. The recovery began 30 minutes later.

--part1\_120.137d8b19.2a6b4c50\_boundary  
Content-Type: text/plain; charset=us-ascii  
Content-Transfer-Encoding: 7bit

```
* * * * *
*      ---REMAINDER OF MESSAGE TRUNCATED---      *
*      This post contains a forbidden message format      *
*      (such as an attached file, a v-card, HTML formatting) *
*      Mail Lists at theporch.com only accept PLAIN TEXT      *
*      If your postings display this message your mail program *
*      is not set to send PLAIN TEXT ONLY and needs adjusting *
* * * * *
```

--part1\_120.137d8b19.2a6b4c50\_boundary--

-----  
Message-ID: <3D39F38A.113AF46E@bw.webex.net>  
Date: Sat, 20 Jul 2002 19:34:34 -0400  
From: Al Klase <skywaves@bw.webex.net>  
MIME-Version: 1.0  
To: Old Tube Radios <boatanchors@theporch.com>  
CC: Old Tube Radios <boatanchors@theporch.com>, K1DW@aol.com, KC1Z@aol.com,  
"Plez Z Reid, W1CCX" <103677.3511@compuserve.com>,  
"Walt, KA1MM" <ka1mm@snet.net>, "Frank Thrash, W4DLZ" <w4dlz@arrl.net>,  
"Frank Thrash @ snakebite" <maryland@snakebite.com>  
Subject: Re: Strange Signal Alert??!!  
Content-Type: text/plain; charset=us-ascii  
Content-Transfer-Encoding: 7bit

Sandy,

Yes, there's stuff at about 13.930, 13.950, 13.985 and  
14.930 14.950 14.960 nearly S9 here in West-central, NJ.  
I'm not much on digital modes, so can't say what it is, but  
it carefully skirts the 20-meter ham band.  
I am hearing digital stuff rather than white noise. Maybe  
two second bursts with 2 second spaces.

Hope this helps a little,  
Al

"Sandy, W5TVW" wrote:

>  
> Hello All,  
> Please listen up on HF. I am getting a signal that sound like someone  
> using AMTOR or PACTOR generating white noise spurious signals.  
> They seem to peak out around 14 and 15 Mhz. but I can't find any  
> signal that matches the timing of the noise.  
> Is anyone else hearing this?  
> Signals on the hambands seems weak to non existant. I  
> suspect a solar blackout or partial one at least.  
> I have seen other funny and wierd signals during severe  
> ionospheric blackout events in the past, this may be the same.  
> Makes me always question my equipment!! I was hearing strange overloading  
> phenomena on my Hallicrafters SR-400's receiver as well.  
>  
> Anyone else having trouble today/last night?  
>  
> 73,  
> Sandy W5TVW

--

Al Klase - N3FRQ  
skywaves@bw.webex.net  
Flemington, NJ 08822  
Web Page: <http://www.webex.net/~skywaves/home.htm>

-----  
From: "Richard Dillman" <ddillman@igc.org>  
To: Old Tube Radios <boatanchors@theporch.com>  
Date: Sat, 20 Jul 2002 17:18:00 -0700  
MIME-Version: 1.0  
Content-type: text/plain; charset=US-ASCII  
Content-transfer-encoding: 7BIT  
Subject: Stuff for sale  
Message-ID: <3D399B48.17076.A0606@localhost>

This from WB6TMY, QTH Nothern California. Please be sure to  
respond directly to him if you're interested in any of his offerings.

RD

----- Forwarded message follows -----  
Date sent: Sat, 20 Jul 2002 10:36:09 -0700



To: Dick Dillman W6AWO <ddillman@igc.apc.org>  
From: W B Reese <\*@radions.net>  
Subject: Stuff for sale

Dear Dick,

I've got some stuff for sale at <http://www.radions.net/buysell.htm> &  
would be grateful if you could post to the boatanchors list!

Thanks,

TR@radions.net  
WB6TMY CFO #1000

----- End of forwarded message -----

Richard Dillman, W6AWO  
Member of the Maritime Radio Historical Society  
<http://www.radiomarine.org>  
Collector of Heavy Metal:  
Harleys, Willys and Radios over 100lbs.

-----  
From: "Richard Dillman" <ddillman@igc.org>  
To: Old Tube Radios <boatanchors@theporch.com>  
Date: Sat, 20 Jul 2002 17:45:20 -0700  
MIME-Version: 1.0  
Content-type: text/plain; charset=US-ASCII  
Content-transfer-encoding: 7BIT  
Subject: Sad TMC  
Message-ID: <3D39A1B0.327.230D5B@localhost>

True fans of TMC equipment are advised to \*not\* look at this  
picture:

<<http://radiomarine.org/tmc.jpg>>

RD

Richard Dillman, W6AWO  
Member of the Maritime Radio Historical Society  
<http://www.radiomarine.org>  
Collector of Heavy Metal:  
Harleys, Willys and Radios over 100lbs.

-----  
Message-ID: <00cf01c23058\$4e3a63e0\$a5a1cdd1@ebjr>  
From: "Sandy, W5TVW" <ebjr@i-55.com>  
To: Old Tube Radios <boatanchors@theporch.com>  
Cc: "Old Tube Radios" <boatanchors@theporch.com>, <K1DW@aol.com>, <KC1Z@aol.com>, "Plez Z Reid, W1CCX" <103677.3511@compuserve.com>, "Walt, KA1MM" <ka1mm@snet.net>, "Frank Thrash, W4DLZ" <w4dlz@arrl.net>, "Frank Thrash @ snakebite" <maryland@snakebite.com>  
Subject: Re: Strange Signal Alert??!!  
Date: Sat, 20 Jul 2002 20:31:10 -0500  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: 7bit

Sounds like it. I have heard some VERY strange stuff during these severe solar events a few times. Makes me wonder what's happening with the queer signals! I have had three rigs fail in the last two days which added to my 'wonderment' about what was going on! It was a combo of bad gear plus screwy ionospheric conditions!  
Thanks for the replies everyone!

73,

Sandy W5TVW

----- Original Message -----

From: "Al Klase" <skywaves@bw.webex.net>  
To: "Old Tube Radios" <boatanchors@theporch.com>  
Cc: "Old Tube Radios" <boatanchors@theporch.com>; <K1DW@aol.com>; <KC1Z@aol.com>; "Plez Z Reid, W1CCX" <103677.3511@compuserve.com>; "Walt, KA1MM" <ka1mm@snet.net>; "Frank Thrash, W4DLZ" <w4dlz@arrl.net>; "Frank Thrash @ snakebite" <maryland@snakebite.com>  
Sent: Saturday, July 20, 2002 6:34 PM  
Subject: Re: Strange Signal Alert??!!

| Sandy,

|

| Yes, there's stuff at about 13.930, 13.950, 13.985 and  
| 14.930 14.950 14.960 nearly S9 here in West-central, NJ.  
| I'm not much on digital modes, so can't say what it is, but  
| it carefully skirts the 20-meter ham band.  
| I am hearing digital stuff rather than white noise. Maybe  
| two second bursts with 2 second spaces.

|

| Hope this helps a little,

| Al

|

| "Sandy, W5TVW" wrote:

| >  
| > Hello All,  
| > Please listen up on HF. I am getting a signal that sound like someone  
| > using AMTOR or PACTOR generating white noise spurious signals.  
| > They seem to peak out around 14 and 15 Mhz. but I can't find any  
| > signal that matches the timing of the noise.  
| > Is anyone else hearing this?  
| > Signals on the hambands seems weak to non existant. I  
| > suspect a solar blackout or partial one at least.  
| > I have seen other funny and wierd signals during severe  
| > ionospheric blackout events in the past, this may be the same.  
| > Makes me always question my equipment!! I was hearing strange overloading  
| > phenomena on my Hallicrafters SR-400's receiver as well.  
| >  
| > Anyone else having trouble today/last night?  
| >  
| > 73,  
| > Sandy W5TVW  
|  
| --  
| Al Klase - N3FRQ  
| skywaves@bw.webex.net  
| Flemington, NJ 08822  
| Web Page: <http://www.webex.net/~skywaves/home.htm>  
|  
|

-----  
Message-ID: <001201c2306e\$3196d6e0\$40dc6843@dave>  
From: "Tom and Silvia Lewandowski" <lewandowski@usfamily.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: Soldering and high impedance phones.  
Date: Sat, 20 Jul 2002 23:21:47 -0500  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="Windows-1252"  
Content-Transfer-Encoding: 7bit

Greetings

I have some older high impedance head phones, and I'm trying to solder some clip leads to the wire ends. The wire consists of about 5 strands of hair-thin wire, that melts when I try to solder it. Does anyone have any suggestions for working with this thin wire? Thanks for your response.

Tom Lewandowski

----- <http://USFamily.Net/info> - Unlimited Internet - From \$8.99/mo! -----

-----  
Date: Sat, 20 Jul 2002 22:16:00 -0700  
Message-ID: <004601c23075\$bc36a580\$0500a8c0@portablechouse>  
From: "ed sharpe" <esharpe@uswest.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: Re: Soldering and high impedance phones.  
MIME-Version: 1.0  
Content-Type: text/plain;  
        charset="Windows-1252"  
Content-Transfer-Encoding: 7bit

wrap a spiral of thin wire around the leand end many times and then flow  
some solder into it.

ed sharpe archivist for smecc

----- Original Message -----

From: Tom and Silvia Lewandowski <lewandowski@usfamily.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Sent: Saturday, July 20, 2002 9:21 PM  
Subject: Soldering and high impedance phones.

> Greetings

>

> I have some older high impedance head phones, and I'm trying to solder  
some

> clip leads to the wire ends. The wire consists of about 5 strands of  
> hair-thin wire, that melts when I try to solder it. Does anyone have any  
> suggestions for working with this thin wire? Thanks for your response.

>

> Tom Lewandowski

>

>

>

> ----- <http://USFamily.Net/info> - Unlimited Internet - From  
\$8.99/mo! -----

>

>

>

-----  
From: "Gary Harmon" <gharmon@idworld.net>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: FW: [Heathkit] WTB: GD-18  
Date: Sun, 21 Jul 2002 08:57:34 -0500

Message-ID: <LKBBJFJHLNHAIBLNCHMEIEBJLMAA.gharmon@idworld.net>  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="Windows-1252"  
Content-Transfer-Encoding: 7bit

Looking to buy a Heathkit GD-18 Electronic Siren and Speaker.

Thanks and 73, gary

=====  
Gary H. Harmon, Jr.  
K5JWK  
6302 Robin Forest  
San Antonio, TX 78239  
(210) 657-1549 <Home>  
(210) 884-6926 <Sprint>  
=====

-----  
Date: Sun, 21 Jul 2002 12:45:42 -0400  
From: "Robert W. Downs" <RWDowns\_WA5CAB@compuserve.com>  
Subject: spam block test  
To: Old Tube Radios <boatanchors@theporch.com>  
Message-ID: <200207211245\_MC3-1-75C-FDC1@compuserve.com>  
MIME-Version: 1.0  
Content-Transfer-Encoding: quoted-printable  
Content-Type: text/plain;  
charset=ISO-8859-1  
Content-Disposition: inline

this is a spam block test. my last msg was blocked.

Robert Downs  
<RWDowns\_WA5CAB@compuserve.com>  
Houston

-----  
Date: Sun, 21 Jul 2002 13:25:31 -0400  
From: "Robert W. Downs" <RWDowns\_WA5CAB@compuserve.com>  
Subject: TM 11-5820-520-35 (AN/GRC-106)  
To: Old Tube Radios <boatanchors@theporch.com>  
Message-ID: <200207211325\_MC3-1-765-96E6@compuserve.com>  
MIME-Version: 1.0  
Content-Transfer-Encoding: quoted-printable  
Content-Type: text/plain;  
charset=ISO-8859-1

Content-Disposition: inline

Groups,

I have an original of the -35 Depot maintenance on the AN/GRC-106. The last page is 4-25 (Figure 4-24). Judging by the later -34 on the 106 and=

106A, it is missing a bunch of pages, but the page numbers in the two manuals don't match up, so I don't know how many. Does anyone have an original that they could check to tell me what's missing?

73

Robert Downs

<RWDowns\_WA5CAB@compuserve.com>

Houston

-----  
Message-Id: <200207211815.g6LIF0og014376@osr506.nanniandjack.com>

From: listtown@nanniandjack.com (Mail List Owner)

To: Old Tube Radios <boatanchors@theporch.com>

Subject: ADMINISTRIVIA: Over Quoting

Date: Sun, 21 Jul 2002 11:15:00 -0700 (PDT)

Gang-

Apparently the gentle nudge and suggestion approach to the issue of improving the quality of posts to the BoatAnchors list, and maintaining our excellent (and high) signal to noise ratio is falling on DEAF EYES!

PLEASE READ THIS AND SAVE IT BECAUSE IT IS IMPORTANT!!!

The list culture is to include only those portions of a prior post that are required to maintain the context of your comments. We have always tried to reduce the amount of "chaf" on the list, and this is one good way.

In private mail between you, a subscriber, and me, as list manager, I really don't care one way or the other, but when posting to the list, there are at least two issues of concern:

- 1) the increased bandwidth from including extra text.  
With the trial subscriptions and full members, the number of copies of each post mailed out change the impact of each extra word so that each single character becomes 1,000 characters of mail!
- 2) by not editing out included text, it sends a not at all subtle message to the list, that the poster considers his/her own time required to merely swipe his mouse across the text and tap the delete

key, to be more valuable than the collective time and energy of the 600-700 readers on the list... not exactly a "positive" message! ;^)

This isn't rocket science... you place the pointer at the top of the message you are including \*parts\* of, and click-drag to where you need to include, and then hit the backspace or delete key... painless, easy, quick, and very helpful to the list.

PLEASE begin to pay attention to this... those who consistently can not be bothered to be considerate of the list will forfeit posting privileges and risk not being invited back for membership.

Treat the list as a symposium. In such an environment, with 600 others attending who have paid to be there, it is unlikely you would repeat someone else's portion of a conversation in its entirety as part of your own remarks... it would become very tedious, very quickly, if you did... especially if you repeated even the closing signature block of the previous message.

Thanks for your understanding and help in making the boatanchors list have the highest signal to noise on the InterNet.

--

73

Jack, W4KH/Mobile - - - BoatAnchor Mailing List Owner - - -  
listown@nanniandjack.com - "Plus ca change, plus c'est la meme chose"  
"Il n'y a que les idiots qui ne changent jamais d'idee"  
Sun Jul 21 11:15:00 PDT 2002

-----  
From: "Richard Dillman" <ddillman@igc.org>  
To: Old Tube Radios <boatanchors@theporch.com>  
Date: Sun, 21 Jul 2002 11:48:16 -0700  
MIME-Version: 1.0  
Content-type: text/plain; charset=US-ASCII  
Content-transfer-encoding: 7BIT  
Subject: Collins 51S-1 Owners?  
Message-ID: <3D3A9F80.15083.3EA528@localhost>

Any Collins 51S-1 owners on the list? A new owner has some questions.

RD

Richard Dillman, W6AWO  
Member of the Maritime Radio Historical Society

<http://www.radiomarine.org>  
Collector of Heavy Metal:  
Harleys, Willys and Radios over 100lbs.

-----  
Date: Sun, 21 Jul 2002 14:51:05 -0400  
From: "Robert W. Downs" <RWDDowns\_WA5CAB@compuserve.com>  
Subject: RE: FWD:USS Requin Needs Tubes & WRT2 Info  
To: Old Tube Radios <boatanchors@theporch.com>  
Message-ID: <200207211451\_MC3-1-789-33CD@compuserve.com>  
MIME-Version: 1.0  
Content-Transfer-Encoding: quoted-printable  
Content-Type: text/plain;  
charset=ISO-8859-1  
Content-Disposition: inline

Groups,

I have in my TM collection the 4" thick 900+ page NAVSHIPS 0967-073-3010  
Operation, Installation, Maintenance and Parts manual on Radio Transmitter  
AN/WRT-2. Before I contact Requin, is there anyone else who needs the  
info? It obviously isn't going to be cheap to copy regardless of who does  
it (there are 100+ 11x24 foldouts as well).

73  
Robert Downs  
<RWDDowns\_WA5CAB@compuserve.com>  
Houston

-----  
Message-ID: <007901c230f2\$1d662ed0\$3201a8c0@w8ut>  
From: "Al Parker" <anchor@ec.rr.com>  
To: Old Tube Radios <boatanchors@theporch.com>  
Subject: Hammarlund Historian Website rebirth  
Date: Sun, 21 Jul 2002 16:06:35 -0400  
MIME-Version: 1.0  
Content-Type: text/plain;  
charset="iso-8859-1"  
Content-Transfer-Encoding: 7bit

Hello all,  
The Hammarlund Historian website is under new management.  
Some of you may have visited the Hammarlund Historian website at its  
new address:  
[www.hammarlund.info](http://www.hammarlund.info)  
in the last few months, and seen some changes. It had been languishing for



several years, after Robert Fowle "abandoned" it, and eventually allowed Al Waller to take custody. Al W. has put it's operation & maintenance in the hands of 4 of us who, together, have a lot of Hammarlund as well as general BA experience.

Barry Hauser, Les Locklear - who had provided most of the historical info to the original site, Andy Moorner, and Al Parker are now overseers. Les has added to the historical info, Andy has been scanning and uploading manuals, Al P. has been working on a new service section and a new overall look for the site.

We hope to have many manuals available for (free) download, many are already there. The new service section has as it's main feature an article by Ray Vasek, W2EC, on re-capping the SP-600, which has been published in Hollow State News, of which Barry Hauser is the editor.

We invite you to take a look at the "new, bright" format and the new features. The old site was sometimes slow in loading, we're trying to help that out. We hope to be adding to the content and making it a source for answers to many of your Hammarlund questions.

73,

Barry H.

Les L.

Andy M.

Al P.

[www.hammarlund.info](http://www.hammarlund.info)

-----  
Message-ID: <008e01c230f2\$480018e0\$3201a8c0@w8ut>

From: "Al Parker" <anchor@ec.rr.com>

To: Old Tube Radios <boatanchors@theporch.com>

Subject: Hammarlund Historian Website rebirth

Date: Sun, 21 Jul 2002 16:07:46 -0400

MIME-Version: 1.0

Content-Type: text/plain;

charset="iso-8859-1"

Content-Transfer-Encoding: 7bit

Hello all,

The Hammarlund Historian website is under new management.

Some of you may have visited the Hammarlund Historian website at it's new address:

[www.hammarlund.info](http://www.hammarlund.info)

in the last few months, and seen some changes. It had been languishing for several years, after Robert Fowle "abandoned" it, and eventually allowed Al Waller to take custody. Al W. has put it's operation & maintenance in the hands of 4 of us who, together, have a lot of Hammarlund as well as general BA experience.

Barry Hauser, Les Locklear - who had provided most of the historical info to the original site, Andy Moorer, and Al Parker are now overseers. Les has added to the historical info, Andy has been scanning and uploading manuals, Al P. has been working on a new service section and a new overall look for the site.

We hope to have many manuals available for (free) download, many are already there. The new service section has as it's main feature an article by Ray Vasek, W2EC, on re-capping the SP-600, which has been published in Hollow State News, of which Barry Hauser is the editor.

We invite you to take a look at the "new, bright" format and the new features. The old site was sometimes slow in loading, we're trying to help that out. We hope to be adding to the content and making it a source for answers to many of your Hammarlund questions.

73,

Barry H.

Les L.

Andy M.

Al P.

[www.hammarlund.info](http://www.hammarlund.info)

-----  
End of BOATANCHORS Digest 3367

\*\*\*\*\*